

# TAP Information No 19 - July 2014

## TTB 4045/4055 Control Board update

As part of Numatic International's commitment to product support and machine upgrades we have made software stability improvements to the control PCB. This will address issues in the field by where you may be experiencing from time to time random brush cut out issues for unexplained reasons.



### WARNING

Please ensure PCB is replaced by a qualified technician.



**Please Request PN:- 323227 when ordering a replacement.**

Compatibility  
TTB 4045 / 4055



 [www.numatic.co.uk](http://www.numatic.co.uk)  
 [www.numatic.fr](http://www.numatic.fr)

 [www.numatic.de](http://www.numatic.de)  
 [www.numatic.nl](http://www.numatic.nl)

 [www.numatic.ch](http://www.numatic.ch)  
 [www.numatic.co.za](http://www.numatic.co.za)

Numatic International Limited, Chard, Somerset, TA20 2GB Tel: +44 01460 68600 Fax: +44 01460 68458  
Specification subject to change without prior notice. TAP000019 Publish Date 09/07/2014